### CARSON, CANADA STATE OF THE LAW AND ASSESSED OF THE LA

### CITY OF CARSON

### PLANNING COMMISSION STAFF REPORT

PUBLIC HEARING:	July 9, 2013
SUBJECT:	Conditional Use Permit No. 937-13
PROPERTY OWNER:	Hector and Luzvinia Lima 162 Lake Washington Drive Kyle, Texas 78640
REQUEST:	To approve a Conditional Use Permit for an existing second dwelling unit located within the RS (Residential, Single-Family) zoning district.
PROPERTY INVOLVED:	2742-2744 East Dominguez Street
CO	MMISSION ACTION
Concurred with staff	
Did not concur with staff	
Other	

### COMMISSIONERS' VOTE

AYE	NO		AYE	NO	
		Chairman Faletogo			Gordon
		Vice-Chair Verrett			Piñon
		Brimmer			Saenz
		Diaz			Schaefer
		Goolsby			

### I. Introduction

Applicant
Paul Siverson
1140 West 3<sup>rd</sup> Street, San Pedro, CA 90731

Property Owner
Hector and Luzvinia Lima
162 Lake Washington Drive, Kyle TX 78640

Project Address 2742-2744 East Dominguez Street

### Project Description

The property owners reside out-of-state. The property owners have designated their listing agent, Paul Siverson, to be the authorized representative regarding this matter. The proposal is to consider approval of Conditional Use Permit (CUP) No. 927-13. The applicant is seeking a determination pursuant to Carson Municipal Code (CMC) Section 9172.21, "Conditional Use Permit" and 9182.3, "Nonconforming Residential Density" for an existing second dwelling unit within the RS (Residential, Single-Family) zoning district located at 2742-2744 East Dominguez Street (Exhibit No. 1).

### II. Background

### Existing Site Conditions/Current Use of Property

The 5,042-square-foot subject property is a relatively flat, rectangular-shaped lot. According to the Los Angeles County Assessor records, the property's lot width is 50-feet with a 102-feet depth. The front yard setback is a well-maintained, landscaped area enclosed with a worn chain link fence. There are two paved driveway approaches located on Dominguez Street; the westerly driveway leads to a one-car garage and the easterly driveway leads to a two-car garage.

There are currently four structures on the subject site: a 791-square-foot, one-story 2-bedroom single family dwelling (primary residence), a detached two-car garage, a 736-square-foot, one-story, 2-bedroom second dwelling unit, and a one-car detached garage. According to building permit records, the primary residence and detached two-car garage were constructed in 1952; and the second dwelling unit and detached one-car garage were built in 1958. The subject property is vacant and has been placed on the market for sale. As a result, before escrow can close, an approved Residential Property Report is required by the City pursuant to Ordinance Nos. 99-1155 and 13-1510 respectively. Staff has been advised that there is a prospective buyer for the subject property.

All of the structures are architecturally similar in terms of features, materials and colors. The second dwelling unit consists of two bedrooms, one bathroom, a living



room and kitchen (Exhibit No. 2). Pursuant to Section 9125.0, the 2-bedroom, 736-square-foot second dwelling unit exceeds the maximum allowable unit size of 700 square feet and is subject to a conditional use permit. However, the CUP addresses all deficiencies on the site.

Previous Proposals/Approved Discretionary Permits
There were no discretionary permits found on record.

Public Safety Issues

There is no open code enforcement case.

### III. Analysis

The second dwelling unit incorporates substantially similar architectural features, building materials and colors as the main dwelling and is compatible with dwellings located on adjacent properties.

Location/Site Characteristics/Existing Development

The project site is located in the east portion of the City located within the Presidential Tract residential development (north of Carson Street, between Alameda Street and Santa Fe Avenue). It is located in a residential neighborhood of single-family homes that were predominantly built in the mid 1920's to mid-century. Price Transfer Incorporation, a freight forwarder business, is located directly across Dominguez Street (north of the property).

### Zoning/General Plan Designation:

The subject property as well as the adjacent properties to the south, east and west are zoned RS (Residential, Single-Family) and has a General Plan land use designation of Low Density. Industrial properties are located north of the subject property within the ML-D (Manufacturing, Light — Design Overlay) zone. The industrial properties were predominantly constructed in the mid 1970's (after the residential tract) with appropriate City approval. As such, the existing single-family dwelling and second dwelling unit are consistent with the RS zoning district and the General Plan land use designation of Low Density along with the designated light industrial uses located across Dominguez Street.

### Conditional Use Permit No. 937-13

Pursuant to CMC Section 9172.21, "Conditional Use Permit", the Planning Commission shall approve the proposal if it is able to make affirmative findings based on the following criteria:

### a. The proposed use and development will be consistent with the General Plan.

The proposed project is consistent with the General Plan of the City of Carson in that the subject property is designated for Low Density Residential and zoned RS (Residential, Single Family). The adjacent properties to the south, east, and west share the same zoning designation and the properties located north are zoned ML-D

Planning Commission Staff Report Conditional Use Permit No. 937-13 July 9, 2013 Page 3 of 7



(Manufacturing, Light – Design Overlay) with a General Plan land use designation of Light Industrial. The ML-D zone is developed primarily for industrial uses which are not likely to have adverse effects upon each other or upon neighboring residential and commercial zones (CMC Section 9113.1); and are subject to site plan and design review so to achieve special standards of design, architectural quality, style and compatibility, and functional integration of neighboring developments (CMC Section 9113.1).

b. The site is adequate in size, shape, topography, location, utilities, and other factors to accommodate the proposed use and development.

The proposed project generally meets the design and development standards in the CMC. CMC Section 9182.3 states, "When approving a conditional use permit, the Commission shall make findings regarding the adequacy of on-site parking and applicable development standards contained in CMC 9125.6."

The second dwelling unit does not meet the following site development standards: minimum lot size (Section 9125.6), minimum front yard setback (Section 9126.23), space between buildings (Section 9126.27), side yard encroachment for a one-story garage (Section 9126.29), rear yard and side yard setbacks (Section 9125.6), and minimum parking requirements (Section 9162.21).

The minimum lot size in order to have a second dwelling unit within the RS zone is 7,500 square feet, the minimum front yard setback to the primary residence is 20 feet, the side yard setback for the second dwelling unit is 5 feet, the rear yard setback is 15 feet, the space between buildings is 6 feet, the side yard encroachment setback for a garage (accessory structure) is 1-inch or 3 feet from the property line and a 2-car garage is required for a second dwelling unit exceeding 700-square-feet.

The property is 5,042 square feet. The front yard setback to the primary residence is 17 feet; the side yard setback for the second dwelling unit is 3 feet; and the rear yard setback for the second dwelling unit is 5.19 feet. There is a 3-foot separation between the two-car garage and second dwelling unit along with a 3-foot separation between the primary residence and one-car garage. The two-car garage is 1-foot from the side yard property line and a one-car garage was constructed for the second dwelling unit.

Additionally, per the requirements in CMC Section 9125.6, a two-bedroom second dwelling unit exceeding 700 square feet is required to provide a two-car garage. The 736-square-foot, two bedroom second dwelling unit and its one-car garage were built in 1958 (prior to the incorporation of the City) with permission from the Los Angeles County Regional Planning Commission and the Building and Safety Division pursuant to Section 733 of Ordinance No. 1494. Pursuant to Section 9125.6, a deed restriction will be recorded with the County Recorder's Office for the second dwelling unit and garage subject to approval of Conditional Use Permit No. 937-13.



CMC Section 9182.3 allows the Planning Commission discretion to determine if the existing nonconformities are appropriate and can continue. In order to prevent further intensifications of non-conformities, staff has included a condition of approval restricting any additions to the property.

Although the site does not meet all the development standards within CMC Section 9125.6, adequate fire and safety access is provided on-site. In addition, a condition of approval is included to ensure all required setbacks are to remain clear for safe access.

CMC Section 9182.3 (B) states, "In the RS or RA Zone, a lawfully established residential use of a type or with a density of dwelling units no longer permitted in the RS or RA Zone shall be considered to be a nonconforming use subject to the provisions of CMC Section 9182.21 through 9282.23." Therefore per CMC Section 9182.21, "conditions may be included which provide for either the continuation or termination of each nonconformity existing on the site" when granting a conditional use permit. Also, CMC 9122.8(C) indicates if standards in CMC 9125.6 are not met then a CUP is required for the existing lawfully established unit.

Since the second dwelling unit was lawfully constructed over 50 years ago and the applicant agrees to the conditions of approval addressing nonconformities, staff recommends the nonconformities be allowed to continue with the approval of a conditional use permit.

The applicant has provided staff with a property inspection report that was prepared by a qualified/certified property inspector, per the requirements of the CUP (Exhibit No. 3). The applicant has addressed the items identified in the property inspection report to the satisfaction of the Planning division and has cleared all of the RPR corrections except obtaining an approved conditional use permit for the second dwelling unit.

With the recommendations stated in the inspection report and conditions of approval, the site and building is considered adequate in size, shape, topography, location, and utilities to accommodate the proposed use.

### c. There will be adequate street access and traffic capacity.

The minimum driveway width is 10-feet. The original driveway leading to the two-car garage is 9 feet wide and the second driveway leading to the one-car garage is 10-feet wide. Staff believes adequate access is available for circulation and provides safety for pedestrians and motorists. Thus, the project will not affect or impact the safe circulation of either pedestrians or vehicular traffic.



### d. There will be adequate water supply for fire protection.

The primary residence and second dwelling unit were constructed and approved in 1952 and 1958, respectively; therefore adequate water supply for fire protection already exists.

e. The proposed use and development will be compatible with the intended character of the area.

The existing two residential units were originally constructed within a single-family neighborhood. The property will not change the intended character of the area as a single-family neighborhood.

f. Such other criteria as are specified for the particular use in other sections of this chapter (Zoning Ordinance).

The proposed project is subject to the requirements in CMC Section 9182.3, "Nonconforming Residential Density" and Section 9125.6, "Second Dwelling Unit Development Standard". The specific requirements of these sections have been discussed above under Section III (b).

Per CMC Section 9182.3 (A), the Commission may require additional improvements to the property, or any buildings or structures thereon, which may include but are not limited to the following:

- 1. New or rehabilitated landscaping;
- 2. Exterior changes to promote compatibility of buildings and structures with surrounding development;
- 3. General repairs to vehicular maneuvering or parking areas; and
- 4. Modifications designed to bring a structure more nearly into compliance with the applicable standards for second dwelling units.

A reasonable and appropriate amount of landscaping is provided within the front yard and areas visible to the public. However, there is an existing dilapidated chain link fence located within the front yard setback and both of the driveways have chipped paint. Staff recommends the chain link fence should be removed or replaced and to repaint or remove the paint from both of the driveways subject to Planning Division approval.

Staff believes the project meets the goals and objectives of the General Plan and is consistent with applicable zoning and design regulations subject to compliance with the conditions of approval. Therefore all of the required findings pursuant to Section 9172.21(D), "Conditional Use Permit, Commission Findings and Decision" and Section 9122.8, "Second Dwelling Units" can be made in the affirmative, if conditions of approval are implemented.

### IV. <u>Environmental Review</u>

The proposed project is categorically exempt from the provisions of the California Environmental Quality Act (CEQA) pursuant to CEQA Guidelines Section 15301, Class 1 – Existing Facilities. The existing second dwelling unit does not have the potential to cause a significant effect on the environment.

### V. Recommendation

That the Planning Commission:

- **APPROVE** Conditional Use Permit No. 937-13 subject to the conditions of approval attached as Exhibit "B" to the Resolution;
- WAIVE further reading; and
- ADOPT Resolution No. 13-\_\_\_\_, entitled "A RESOLUTION OF THE PLANNING COMMISSION OF THE CITY OF CARSON APPROVING CONDITIONAL USE PERMIT NO. 937-13 FOR AN EXISTING SECOND DWELLING UNIT FOR A PROPERTY LOCATED AT 2742-2744 EAST DOMINGUEZ STREET."

### VI. Exhibits

- 1. Draft Resolution
- 2. Site Map
- 3. Property Inspection Report for 2744 East Dominguez Street

4. Development Plans (submitted under separate cover)

Prepared by:

McKina Alexander, Planning Technician

Reviewed by:

John F. Signo, AICP, Senor Planner

Approved by:

Sheri Repp, Plahning Officer

### CITY OF CARSON

### PLANNING COMMISSION

### RESOLUTION NO.

A RESOLUTION OF THE PLANNING COMMISSION OF THE CITY OF CARSON APPROVING CONDITIONAL USE PERMIT NO. 937-13 FOR AN EXISTING SECOND DWELLING UNIT FOR A PROPERTY LOCATED AT 2742-2744 EAST DOMINGUEZ STREET

THE PLANNING COMMISSION OF THE CITY OF CARSON, CALIFORNIA, HEREBY FINDS, RESOLVES AND ORDERS AS FOLLOWS:

**Section 1.** An application was duly filed by the authorized agent and applicant, Paul Siverson on the property owner's behalf, with respect to real property located at 2742-2744 East Dominguez Street, and described in Exhibit "A" attached hereto, requesting the approval of a second dwelling unit located within the RS (Residential, Single Family) zoning district. The second dwelling unit is located in the rear of the property and the one-car garage is located west of the front primary house. The 736-square-foot, two bedroom second dwelling unit and detached one-car garage (10' x 20') were legally constructed in 1958, prior to the adoption of Ordinance No. 03-1290 in 2003, which requires a conditional use permit for legal nonconforming second dwelling units that do not meet the development standards in Section 9125.6 of the Carson Municipal Code (CMC).

A public hearing was duly held on July 9, 2013, at 6:30 P.M. at City Hall, Council Chambers, 701 East Carson Street, Carson, California. A notice of time, place and purpose of the aforesaid meeting was duly given.

**Section 2**. Evidence, both written and oral, was duly presented to and considered by the Planning Commission at the aforesaid meeting.

### Section 3. The Planning Commission finds that:

- a) The existing second dwelling unit meets the goals and objectives of the General Plan and is consistent with applicable zoning and design regulations. The proposed project is identified in the Carson Municipal Code as a permitted use for this land use category subject to Conditional Use Permit approval. The adjancent properties are developed with residential single family dwellings with light industrial uses located north of the subject property (across Dominguez Street). The proposed project is compatible with the neighborhood.
- b) The site is adequate in size, shape, topography, location, and utilities to accommodate the second dwelling unit. The second dwelling unit is not in conformance with minimum lot size, unit size, setback and parking requirements, but it is permitted through approval of a Conditional Use Permit.
- c) The property will not generate or intensify non-conformities with the implementation of conditions of approval. The conditions of approval contained in Exhibit "B" of this Resolution restrict future expansions and/or additions to the site unless site development standards are met. Adequate driveways are provided on-site and the project will not affect or impact the safe circulation of either pedestrian or vehicular traffic. All parking areas and driveways shall



remain clear to facilitate automobile parking and access. No encroachment into parking areas and/or driveways shall be permitted.

- d) The size, shape, and topography of the site are similar in nature to the other adjacent residential properties with legal nonconforming second dwelling units. Like other surrounding properties the site does not meet the minimum lot size for a second dwelling unit since it was originally constructed in 1958, prior to the City's incorporation and ordinance. The City's current ordinance requires a two-car garage for a second dwelling that exceeds 700-square-feet or consists of two bedrooms. The 936-square-foot, two bedroom second dwelling unit and detached one-car garage were constructed with appropriate approvals by the Los Angeles County Regional Planning Commssion and Building and Safety Division in accordance to the code at that time.
- e) Adequate water supply is provided.
- f) The second dwelling unit generally conforms to all applicable design standards and guidelines that have been adopted pursuant to Section 9125.6, "Second Dwelling Unit Development Standards" of the Carson Municipal Code.
- g) All of the required findings pursuant to Section 9171.21(d), "Conditional Use Permit, Approval Authority and Findings and Decision" can be made in the affirmative.

**Section 4.** The Planning Commission further finds that the second dwelling unit will not have a significant effect on the environment. The second dwelling unit will not alter the predominantly residential single family character of the surrounding area and meets or exceeds all city standards for protection of the environment. Therefore, the proposed project is found to be categorically exempt under the California Environmental Quality Act (CEQA) Guidelines, Section 15301 (Existing Structures or Facilities).

**Section 5**. Based on the aforementioned findings, the Planning Commission hereby approves the categorical exemption and grants Conditional Use Permit No. 937-13 with respect to the property described in Section 1 hereof, subject to the conditions set forth in Exhibit "B" attached hereto.

**Section 6**. The Secretary shall certify to the adoption of the Resolution and shall transmit copies of the same to the applicant.

**Section 7**. This action shall become final and effective fifteen days after the adoption of this Resolution unless within such time an appeal is filed with the City Clerk in accordance with the provisions of the Carson Municipal Code.

PASSED, APPROVED AND ADOPTED THIS 9th DAY OF JULY, 2013.

ATTEST:	CHAIRMAN
SECRETARY	
MA/c937-13 070913	



PRELIMINARY REPORT YOUR REFERENCE: 7575MR Ticor Title Company of California ORDER NO.: 00158221-996-SL4

### EXHIBIT "A"

### LEGAL DESCRIPTION

THE LAND REFERRED TO HEREIN BELOW IS SITUATED IN THE COUNTY OF LOS ANGELES, STATE OF CALIFORNIA, AND IS DESCRIBED AS FOLLOWS:

Lot(s) 1019 and 1020, of Tract No. 7644, in the City of Carson, County of Los Angeles, State of California, as per Map recorded in Book 84, Page(s) 47 and 48 inclusive of Maps, in the office of the County Recorder of said County.

APN: 7308-003-017



### CITY OF CARSON

### **DEVELOPMENT SERVICES**

### PLANNING DIVISION

### EXHIBIT "B"

### CONDITIONS OF APPROVAL

### **CONDITIONAL USE PERMIT NO. 937-13**

### **GENERAL CONDITIONS**

- 1. If Conditional Use Permit No. 937-13 is not used within one year of their effective date, said permits shall be declared null and void unless an extension of time is previously approved by the Planning Commission.
- 2. In order to prevent further intensifications of non-conformities, restriction of future expansions and/or additions to the site unless site development standards are met subject to Planning Commission approval.
- 3. The dilapidated chain link fence located within the front yard setback shall be either removed or replaced subject to the Planning Division approval.
- 4. The chipped paint located on both driveways shall be removed or stripped and repainted subject to the Planning Division approval.
- 5. All required setbacks are to remain clear for safe access.
- 6. Approval by the Planning Division and issuance of appropriate building permits, if applicable, are required for any future alterations, expansions or repairs.
- 7. The applicant shall comply with all city, county, state and federal regulations applicable to this project.
- 8. The applicant shall make any necessary site plan and design revisions to the site plan and elevations approved by the Planning Commission in order to comply with all the conditions of approval and applicable Zoning Ordinance provisions. Substantial revisions will require review and approval by the Planning Commission.
- 9. The applicant and property owner shall sign an Affidavit of Acceptance form and submit the document to the Planning Division within 30 days of receipt of the Planning Commission Resolution.
- 10. The applicant shall submit two complete sets of plans that conform to all the Conditions of Approval to be reviewed and approved by the Planning Division within 90 days of receiving approval by the Planning Commission, if applicable.

COA c937-13 Page 1 of 3



- 11. The approved Resolution, including the Conditions of Approval contained herein, and signed Affidavit of Acceptance, shall be copied in their entirety and placed directly onto a separate plan sheet behind the cover sheet of the development plans and submitted to Planning division.
- 12. Decision of the Planning Commission shall become effective and final 15 days after the date of its action unless an appeal is filed in accordance with Section 9173.4 of the Zoning Ordinance.
- 13. A property inspection report was prepared by a qualified/certified property inspector that includes plans to eliminate or mitigate any building, plumbing, electrical and fire code deficiencies. The deficiencies described in the inspection report shall be eliminated or mitigated within 90 days to the satisfaction of the Planning Division. The Planning Division shall inspect the property for compliance with the corrective measures. An extension of time to complete necessary corrective measures may be granted for up to an additional 90 days, subject to the discretion of the Planning Division.
- 14. Per Carson Municipal Code Section 9125.6.8 (L)(1), the applicant shall submit a deed restriction stating that:
  - a. The second dwelling unit shall not be sold separately;
  - b. The second dwelling unit is restricted to the maximum size allowed per the conditional use permit; and
  - c. The restrictions shall be binding upon any successor in ownership of the property and lack of compliance shall void the approval of the unit and may result in legal action against the property owner.
- 15. The deed restriction shall be recorded at the County Recorder's Office within 90 days after it is reviewed and approved by the Planning Division. Proof of recordation shall be furnished to the Planning Division.
- 16. The property owner shall consent to an inspection of the interior and exterior of all buildings upon receipt of a written request by the City in order to determine compliance with these conditions and applicable Carson Municipal Code requirements.
- 17. A modification of the conditions of this permit, including additions or deletions, may be considered upon filing of an application by the owner of the subject property or his/her authorized representative in accordance with Section 9173.1 of the Zoning Ordinance.
- 18. It is further made a condition of this approval that if any condition is violated or if any law, statute, or ordinance is violated, this permit may be revoked by the Planning Commission or City Council, as may be applicable; provided the applicant has been given written notice to cease such violation and has failed to do so for a period of thirty days.

COA c937-13 Page 2 of 3



19. The Applicant shall defend, indemnify and hold harmless the City of Carson, its agents, officers, or employees from any claims, damages, action, or proceedings against the City or its agents, officers, or employees to attack, set aside, void or annul, an approval of the City, its advisory agencies, appeal boards, or legislative body concerning Conditional Use Permit No. 937-13. The City will promptly notify the Applicant of any such claim, action, or proceeding against the City and the Applicant will either undertake defense of the matter and pay the City's associated legal costs or will advance funds to pay for defense of the matter by the City Attorney. The City will cooperate fully in the defense. Notwithstanding the foregoing, the City retains the right to settle or abandon the matter without the Applicant's consent but should it do so, the City shall waive the indemnification herein, except, the City's decision to settle or abandon a matter following an adverse judgment or failure to appeal, shall not cause a waiver of the indemnification rights herein.

### **PARKING**

- 20. Designated parking shall meet all applicable standards as outlined in the City of Carson development standards. No expansions, additions, or landscaping shall be constructed that precludes or prevents on-site parking.
- 21. Designated parking shall be provided on-site for the primary and secondary unit. A total of two garages (one detached 2-car garage for the primary dwelling and one, one-car garage for the second dwelling unit) shall be provided on-site.
- 22. All parking areas and driveways shall remain clear to facilitate automobile parking and access. No encroachment into parking areas and/or driveways shall be permitted.

### **BUILDING & SAFETY**

23. All building improvements shall comply with City of Carson Building and Safety Division requirements.


### FIRE DEPARTMENT - COUNTY OF LOS ANGELES

- 24. All requirements by the Los Angeles County Fire Department shall be met.
- 25. There shall be no storage allowed within any required building setback yard area to promote fire safety.

### BUSINESS LICENSE DEPARTMENT - CITY OF CARSON

26. Per section 6310 of the Carson Municipal Code, all parties involved in the project, including but not limited to contractors and subcontractors, will need to obtain a City Business License.

Page 3 of 3





City of Carson 500 Foot Radius Map 2742-2744 E. Dominguez Street

Kinddresses/Dominguoz, 5/1/2742-2744/UP 997-13PC Notices ZerningNap2. III



This is to certify that

### Dimas Avila

Ins Successfully Completed

# 

A Kaplan Professional Company

### 

## FIGUROLIUM PROPERTY

May 13-24, 2002

continuing education crédi State regulatory entities a Associations for 90 hours This course is approved most flome Imspection

Classroom and Field Train! Examinations have b laken and passed in:

Air Conditioning Report Writing Roofing Plumbing Structures Standards Exteriors Fleetrical Fleating Interior



THIS TIME PERIOD IS SHORTER THAN OTHERWISE PROVIDED BY LAW.

MAY 13 2013

This Agreement shall be binding upon and inure to the benefit of the parties hereto and their heirs CITY OF CARSON before any lawsuit is filed. All notices of mediation must be control in writing by return receipt requested successors, and assigns.

This Agreement constitutes the entire integrated agreement between the parties hereto pertaining to the subject matter hereof and may be modified only by a written agreement signed by all of the parties hereto. No oral agreements, understandings, or representations shall change, modify, or amend any part of this Agreement.

Each party signing this Agreement warrants and represents that he/she has the full capacity and authority to execute this Agreement on behalf of the named party. If this Agreement is executed on behalf of Client by any third party, the person executing this Agreement expressly represents to Inspector that he/she has the full and complete authority to execute this Agreement on Glient's behalf and to fully and completely bind Client to all of the terms; conditions, limitations, exceptions, and exclusions of this Agreement.

SEVERABILITY: Should any provision of this Agreement be held by a court of competent jurisdiction to be either invalid or unenforceable, the remaining provisions of this Agreement shall remain in full force and effect, unimpaired by the court's holding.

**MEDIATION:** The parties to this Agreement agree to attend, in good faith, mediation with a retired judge or CARSON, CA 90745be served in writing by return receipt requested allowing 30 days for response. If no response is forthcoming the moving party may then demand binding arbitration under the terms and provisions set forth below.

> ARBITRATION: Any dispute concerning the interpretation or enforcement of this Agreement, the inspection, the inspection report, or any other dispute arising out of this relationship, shall be resolved between the parties by binding arbitration conducted in accordance with California Law, except that the parties shall select an arbitrator who is familiar with the real estate profession. The parties agree that they shall be entitled to discovery procedures within the discretion of the arbitrator. The arbitrator shall manage and hear the case applying the laws of the State of California to all issues submitted in the arbitration proceeding. The award of the arbitrator shall be final, and a judgment may be entered on it by any court having jurisdiction. Any disputes are to be arbitrated by:

Judicial Arbitration and Mediation Service (JAMS®)

Report #:		
Ment: Beatrize Rios	inspection fee: $\$$ $490$ .	
uddress;	INSPECTION FEE: \$ 49.0. —  disch fee: \$ -9.b	
City, State, Zip:	TOTAL FEE: \$	
Phone: 562-502-038D	Form of Payment: May 19Rdy	

Client acknowledges having read and understood all the terms, conditions, and limitations of this Agreement and voluntarily agrees to be bound thereby and to pay the fee listed above.



contract includes the pront of this page  ${=}$ 

### PAGES INSPECTION REPORT

PAGES INCLUDED ARE:

**GROUNDS** 

**FOUNDATION** 

EXTERIOR

Page 7

**ROOF** 

Page 10 HEATING 2 & A/C

Page 8 PLUMBING

Page 9 HEATING 1

Page 11 ELECTRICAL

Page 1/2 CONTRACT

KEY

Page 3

Page 4

Page 6

Page 5

ght. (C)

The "Matrix" Report lists the systems and components inspected by this company. Items not found in this report are considered beyond the scope of this inspection, and should not be considered inspected at this time.

When "APPEARS SERVICEABLE" is checked it means that we did not observe conditions that would lead us to believe problems existed with this system or component. The item is capable of being used. Some serviceable items may, however, show wear and tear. Other conditions are checked, if applicable, in the body of the report.

Significantly deficient systems or components will be identified as: Not functional/unsafe/worn/near end of lifespan. The reason an item is "significantly deficient" will be checked within the body of the report. Review these findings and take "governmended actions before close of the transaction. Please read the entire report for all items checked.

NOTICE: This report contains technical information. If you were not present during this inspection please call the office to arrange for a verbal consultation with your inspector. If you choose not to consult with the inspector, this inspection company cannot be held liable for your understanding or misunderstanding of this report's contents.

cannot be held liable for your understanding	or misunderstanding of this report's contents.
	an (*) Asterisk next to them: This item or component warrants tion, repair or monitoring.
City and a second secon	a (①) Circled Number next to them: mbers are defined as follows:
Recommend further review by	a qualified licensed structural engineer/geotechnical engineer.
Recommend further review ar tradesman dealing with that it	nd repairs as needed by a qualified licensed contractor or specialty em or system.
Recommend further review for by a qualified Pest Inspector.	the presence of any wood destroying pests or organisms
4 This item is a safety hazard -	correction is needed.
before the era of current safety	or safety enhancement. This building may have been built standards.  VERSION OF THIS KEY IS PRINTED AT THE TOP OF EACH PAGE
Please read the special "NOTICES" limitations of this inspection.	in each section of the report for further information concerning the
If you do not unders	tand how to read this report please contact our office
PRESENT DURING THE INSPECTION:	
WEATHER CONDITIONS: L Dry L INSPECTION DATE: START TIA	Rain today / Recently Snow today / Recently TEMP F AE: 500 FINISH TIME: 6 10 INSPECTOR:
PROPERTY INFORMATION:	
Single family Duplex Trip Townhome Condominium	lex Fourplex Residential Units Commercial Industrial
Occupied Vacant I	Partial furnishings
Approximate age of building: 70+	Stated by: Unknown
Approximate age of roof:	Stated by: Unknown
Additions or Alterations:	NOTICE: It is always wise to check with the building department for permit information, especially if additions or alterations are noted.

Optional Pages:

POOL/SPA

PERMIT REVIEW

**GENERAL NOTES** 

REPORT OVERVIEW

**STANDARDS** 

Page 12 INTERIOR 1

Page 13 INTERIOR 2

Page 16 BATHROOM

GARAGE

KITCHEN

Page 14

Page 15

	GROU	NDs 🕏	10 10			
KEY:	② Recommend	evaluation and repa	ictural/geo-technical airs by a licensed con or further information	tractór 🔞 Upgrades	s a safety hazard - correction are recommended for safet warrants attention/repair or	enhancement
Drive	way J	♦ ASPHAIT	ONCRETE	♦ GRAVEL	<b>*</b>	gyak <sup>al</sup> dhiyydiyyyraanoeetttaissa Eestessia Maasaanaetti (NAA)innooniasi wasa kuula A
☐ Erod	ed Asphalt*	☐ Maintenance	/ sealant needed*	Near end of lifespan' Evidence of de s* Q Surface raised	Not fully visible: sterioration / poor drains / settled / trip hazards*_	ige*
Siden	falks (A)	♦ CONCRETE	♦ BRICK	♦ PAVER / TILE	♦ GRAVEL	<b>\$</b>
O No	cracks found crete is above fo	Common cra	cks 🛛 Major cracl	cs* 🔲 Surface raised	*	
Remin	ng Walls	LOCATION(S):	THE PUBLISHED NAMES AND THE PROPERTY OF THE PUBLISHED WAS TO STATE	_   CONCRETE/BLC	OCK / STUCCO / WOOD	And the state of t
□ No c	ear serviceable cracks found NTS:	☐ Common cra			tration / No drainage or	Not fully visible* enings*
Patio	N/A)	LOCATION(S):		� CONCRETE/BRI	CK/PAVER TILE/BLOCK	
□ No o	cracks found	✓ Common cra undation/siding	ıcks 🛛 Major crac	ks* 🚨 Surface raised	* O Not fully visible. / settled / trip hazards* por drainage*	
DECK PATTO PORCH	Cover A	LOCATION(S):		OPEN DESIGN/	COVERED ROOF (REFER TO	ROOF PAGE*)
□ App □ Uns	ears serviceable	· D Not function attachment to hou	al/Unsafe/Worn use* 🛛 Lacks: me	/Near end of lifespan tal straps/bolts/nails	* Q Not fully visible	
COMME	NTS;	7/.				·
Deck	s/Rorein H	ï WOOD	♦ CONCRETE	♦ WATERPROOF C	OATING	
☐ App ☐ Crac ☐ Dec ☐ Porc ☐ Scre	ears serviceable cks/Moisture stai k appears unsou h/steps settled a ens/panels damag ings are service	ns/damage@@_ and @@ way from house*_ ed/torn/missing*_	Deck on gra Flashing n Uneven ste Unable to d	B Near end of lifespan* ade - unable to inspect* ot visible / improper@ ep(s) at porch / deck*@ etermine active leakage* naged / loose / too low*	☐ Flashing missing ☐ Earth-to-wood c ☐ Evidence of poo	raps/footings@ g at house@ ontact® r drainage*
e jejneas	& Grites (NA)	♦ FENGES, NOTE	NSPECTED)	♦ WOOD / CHAIN	LINK/WROUGHTIRON/M	ASONRY
☐ Loo		Loose/miss  Major crack	ing blocks*	☐ Broken/loose ning*☐ Fence at pool/	* D Not fully visible / missing boards* D spa area is: missing / too te / latch is: missing / not wor	l Moisture damage* low / climbable*@§
convigat (C)		ING L.T.A. REPRODUCTION	OR UTILIZATION OF THIS REP	ORT WITHOUT WRITTEN AUTHORIZ	ATION BY L.T.A. IS NOT PERMITTED	6X2HFX0401 4

	IROR PER L
· ② Recomi	mend evaluation by a structural/geo-technical engineer mend evaluation and repairs by a licensed contractor by qualified termite report for further information This item is a safety hazard - correction is needed Upgrades are recommended for safety enhancement This item warrants attention/repair or monitoring
Exterior Stairs	♦ WOOD / METAL / CONCRETE / WATERPROOF COATING
O Moisture stains,	able □ Not functional / Unsafe / Worn / Near end of lifespan* □ Not fully visible:
Exterior Walls	STRUCTURE:
☐ No cracks found	able D Not functional / Unsafe / Worn / Near end of lifespan* D Not fully visible:
Notice: Wall insulation typ	se and value is not verified.* UFFI insulation or hazards are not identified.* Conditions inside the wall cannot be judged.* Lead paint testing is not performed.*
O Trim	N/A    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / WOOD / METAL / VINYL / BRICK / CONCRETE / MASONRY    WOOD / WOO
☐ Moisture stains /	ia & trim appear serviceable  Not functional / Unsafe / Worn / Near end of lifespan*  Not fully visible / damage at: eaves / soffits / facia / corner / window / wall trim  (Caulking / paint / finish needed* damaged / loose / cracks / missing / not visible at: eaves / soffits / facia / corner / window / wall trim (2)
i Chimney(s)	LOCATION(S) A B C D  A/A  D  M/A  D  METAL FLUE / WOOD FRAME: STUCCO / SIDING
☐ Chimney / brick / ☐ Spark'screen pres ☐ Cracks or separ	ble
Notice: The interior of the	flue was not inspected at this time. We recommend that you retain a qualified chimney sweep to clean and evaluate the live*
2 Sprinklers 💎 🖁	NA Not inspected*   Automatic timers not tested*  Control box location:
☐ Appear service ☐ Valve/head/li ☐ Adjust spray aw COMMENTS:	able
	nes cannot be judged for breaks or possible root intrusions. Association-maintained systems are not tested. Grove systems are not tested."
3 Hose Fauceis	Not inspected* The Frost type: yes/no* Winterized - not tested* Anti-siphon valves: yes/no*
Appear service	able ☐ Some inoperative / corroded ② ☐ Leaks② ☐ Missing / broken handle(s)*
Gutters & Downspouts	NA PARTIAL NONE INSTALLED
☐ Appear service ☐ Drains blocked ☐ Add gutters & c ☐ Roof / gutters n	able D Not functional / Unsafe / Worn / Near end of lifespan* D Not fully visible:

"KEY: ① Recommend	evaluation by a struct	ural/geo-technical eng s by a licensed contrac	ineer @ This item is a	safety hazard - correction	on is needed
® Refer to qualit	red termite report for	opy a licensed contraction	* This item war	recommended for safet rants attention/repair or	y ennancement r monitoring
Grading NA	( LEVEL SITE	SLOPE MINOR/A	AODERATE/STEEP ① / S	STAIRSTEPPED	♦ BANKS
☐ Drainage of site/slope	of soil at foundation	is proper based upon	visual observation	Q Not fully visible*.	
Improper soil slope to	ward foundation*	☐ Soil / pavement	is high at foundation*		
☐ Plants / trees touch he		☐ Trees planted c		Overgrown land	
<ul> <li>Surface drains noted,</li> </ul>	not testedunderg	round pipes cannot	be judged *	[Ja] Signs of poor dra	ainage/erosion*
COMMENTS:			<u></u>		
Notice: This inspection goes not in	clude acatgă (cai conditions o	site stability information. For	intormation concerning these com	dillons, a neologist or soils engin	eer should be consulted.
♦ Slab-on-grade				maryan nga paga paga paga paga paga paga pag	
FOUNDATIONS: POU			State of the state	Fy / & LEST MICHES E	♦ NONE
COLUMNS: CONCRETE				D ) INC)   A 1'3808'E	♦ NONE
☐ Entered crawl space				cess opening only*	V
Door / cover: OK					
undations:	٠. ٥		☐ Not visible at*		
Appear serviceable				☐ Further evaluation	on needed ①
No cracks found	A Common cracks	/deterioration*	☐ Major cracks / d	eterioration/bulges,	/ movement ①
No cracks found No moisture present	<sup>™</sup> Moisture / stair	ns/damage*	☐ Excessive moist	ure /-damage ①	☐ Exposed footing
Unable to inspect: v	/alls/frame/floor	due to: furniture/c	abinetry/stored-iten	ns/paneling/tile/flo	oor coverings*
Li blab visible / not visit	ile due to carpet an	d moor coveringno	readily visible proble	m noice logay	
U Slab visible (not visible due t	ole due to carpet and carpet and	a noor covering-no coveringrecommei	readily visible proble and further evaluation in	m noted today  byremoval-officor co	overing due to: —
Q Slab not visible due to	o carpet and floor o	overingrecomme	nd further evaluation	by removal of floor co	overing due to: — cterior walls ① ←
☐ Slab visible (not visible due to ☐ Slab not visible due to ☐ Cracks found*  NTILATIONN/A	o carpet and floor of Uneven areas	coveringrecomment in flooring*	nd further evaluation Unusual cracks	by removal of floor co found on interior / ex	cterior walls ① 🗢
☐ Slab not visible due t ☐ Cracks found* NTILATIONN/A	o carpet and floor of Uneven areas  Serviceable	coveringrecomment in flooring* • Vents blocked	nd further evaluation Unusual cracks	by removal of floor co found on interior / ex	cterior walls ① 🗢
☐ Slab not visible due t	o carpet and floor of Uneven areas  Serviceable	coveringrecomment in flooring* • Vents blocked	nd further evaluation Unusual cracks	by removal of floor co found on interior / ex	cterior walls ① 🗢
☐ Slab not visible due t ☐ Cracks found* NTILATIONN/A	o carpet and floor of Uneven areas  Serviceable	coveringrecomment in flooring* • Vents blocked	nd further evaluation Unusual cracks	by removal of floor co found on interior / ex	cterior walls ① 🗢
☐ Slab not visible due t ☐ Cracks found* NTILATIONN/A	o carpet and floor of Uneven areas  Serviceable	coveringrecomment in flooring* • Vents blocked	nd further evaluation Unusual cracks	by removal of floor co found on interior / ex	cterior walls ① 🗢
O Slab not visible due to Cracks found*  NTILATIONN/A	o carpet and floor of D Uneven areas  Serviceable	overingrecomment in flooring*  • Vents blocked	nd further evaluation  Unusual cracks  / needed ②	by removal of floor confound on interior / ex ☐ Vent screen(s) da	cterior walls ① ← amaged / missing
O Slab not visible due to Cracks found*  NTILATION N/A  COMMENTS:  Notice: All slabs experience some degree inspector will, at additional cost, relinspector will, at additional cost, and a cost, and	o carpet and floor of Uneven areas  O Serviceable  of cracking due to stankage in act, provided the client removes to	overingrecomment in flooring*  O Vents blocked block	nd further evaluation  Unusual cracks / needed ②  stoor coverings prevent recognition actor from damage caused by this proc	by removal of floor confound on interior / exfound on interior / ex  U Vent screen(s) do  proceed the screen of th	cterior walls ① ← amaged / missing
O Slab not visible due to Cracks found*  O Cracks found*  NTILATIONN/A  COMMENTS:  Notice: All slabs experience some degree inspector will, at additional cost, reinspo	o carpet and floor of Uneven areas  Uneven areas  Serviceable  of cracking due to shrinkage in the string due to shrinkage i	in flooring*  O Vents blocked  The drying process, in most instance and covering and releases the insign	Indifurther evaluation  Unusual cracks  I needed ②  stillour covertings prevent recognition of the foundamage caused by this processor from damage caused by this processor.	by removal of floor confound on interior / ex ☐ Vent screen(s) da	cterior walls ① ← amaged / missing
O Slab not visible due to Cracks found*  NTILATION N/A  COMMENTS:  Notice: All stabs experience some degree inspector will, at additional cost, rainspool of the construction:  OOD FRAME:	O carpet and floor of Uneven areas  Uneven areas Serviceable  or of tracking due to shrinkage in text, provided the client removes if  JOISTS CONVENTIONA	overingrecomment in flooring*  Uents blocked	Indifurther evaluation  Unusual cracks  I needed   sfloorcoverings prevent recognitions  color from damage caused by this proc  CONCRETE  TRUSS	by removal of floor confound on interior / exfound on interior / ex  \[ Vent screen(s) do  of crasks or settlement in all but the many conformation of the many confo	cterior walls ① ← amaged / missing ostsevere cases. The during this inspection.
O Slab not visible due to Cracks found*  O Cracks found*  NTILATIONN/A  COMMENTS:  Notice: All status experience some degree inspector will, at additional cost, reinspector of the construction:  OOR CONSTRUCTION:  OOD FRAME:  O Appears serviceable	O carpet and floor of Uneven areas Uneven areas Serviceable  Bet pracking due to shrinkage in the city provided the client removes to possess O JOISTS CONVENTIONAL UNot functional	in flooring*  O Vents blocked  Trusses  WOOD FRAMING  Unsafe/Wom/Neare	TONCRETE  Cond of lifespan*	by removal of floor confound on interior / exfound on interior / exfound on interior / exformed of the conformed of the confo	cterior walls ① ← amaged / missing ostsevere cases. The during this inspection.*
O Slab not visible due to Cracks found*  O Cracks found*  NTILATIONN/A  COMMENTS:  Notice: All status experience some degree inspector will, at additional cost, reinspector will, at additional cost, reinspector will at a different	o carpet and floor of Uneven areas Uneven areas Serviceable  entracking due to shrinkage in act, provided the client removes to CONVENTIONAL Not functional/	in flooring*  O Vents blocked  be drying process, in most instance or covering and releases the inspect  TRUSSES  WOOD FRAMING  Unsafe/Worn/Near of Missing framin	of further evaluation  Unusual cracks / needed ②  stiourcoverings prevent recognition a coter from damage caused by this proc  CONCRETE  TRUSS end of lifespan* ng strap(s) / block(s) ②	by removal of floor confound on interior / exfound on interior / exfound on interior / exfound on interior / exformential interior ess. Floor coverings are not removed  NOT VISIBLE  Not fully visible  Moisture stains /	cterior walls ① ← amaged / missing ostsevere cases. The during this inspection.*  * / damage ②③
O Slab not visible due to Cracks found*  NTILATIONN/A  COMMENTS:  Notice: All slabs experience some degrinspector will, at additional cost, reinspector will, at additional cost, rein	o carpet and floor of Uneven areas Uneven areas Serviceable  of cracking due to strinkage in the string due to strinkage in string provided the client removes to the string of the stri	in flooring*  Wents blocked  TRUSSES  WOOD FRAMING  Unsafe/Worn/Neare  M Missing framinosts/beams ®	strap(s) / block(s) @  Earth-to-wood of	by removal of floor confound on interior / exfound on interior / exfound on interior / exfound on interior / exfound on interior / exformed of ventor settlement in all but the meass. Floor coverings are not removed.  NOT VISIBLE  Not fully visible of Moisture stains / contact ©	cterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ② ③ ebris under house*
O Slab not visible due to Cracks found* Cracks found* NTILATIONN/A COMMENTS:  NOTICE: All status experience some degree inspector will, at additional cost, reinspector will, at addit	e of cracking due to statukage this bet, provided the client removes to \$\int\text{ONVENTIONAL}\$ \( \text{ONVENTIONAL}\$ \( \text{ONVENTIONAL}\$ \( \text{of functional} / \text{g framing } \text{@} \) unsecured piers / \( \text{p} / \text{columns appear:} \)	to vering-recomment in flooring*  O Vents blocked to verify the drying process, in most instance or covering and releases the insign of the verify that is a very large of the verify that is a very large of the	sticor coverings prevent recognition actor from damage caused by this proceed to the transfer of the transfer	by removal of floor confound on interior / exfound on interior stains / exfound of the interior	eterior walls ① <a href="mailto:amaged/missing">amaged/missing</a> Distribution of the during this inspection.  *  / damage ② ③  Petris under house*  tied / rotted ②
O Slab not visible due to Cracks found* Cracks found* NTILATION_N/A COMMENTS:  NULCE: All stabs experience some degree inspector will, at additional cost, reinspector of the control of	© carpet and floor of Uneven areas  ☐ Uneven areas ☐ Serviceable  ☐ Serviceable ☐ Serviceable ☐ OUTTONAL ☐ Not functional/ g framing ② unsecured piers/ / columns appear: perly sloped*/cracket	TRUSSES WOOD FRAMING Unsafe/Wom/Neare  "Maissing framing overspanned/bea ed*/deteriorated*/se	TONCRETE  O TRUSS  CONCRETE  TRUSS  Cond of lifespan*  ag strap(s) / block(s) ©  Earth-to-wood oring poorly / twisting / attled ©	by removal of floor confound on interior / exfound on interior / exfound on interior / exfound on interior / exfound on interior / exformed of ventor settlement in all but the meass. Floor coverings are not removed.  NOT VISIBLE  Not fully visible of Moisture stains / contact ©	cterior walls ① ← amaged / missing ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* sted / rotted ② ure/water present*
☐ Slab not visible due to ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ NA COMMENTS: ☐ Notice: All status experience some degree laspector will, at additional cost, refinspector of the composition	© carpet and floor of Uneven areas  □ Uneven areas □ Serviceable  □ Sorviceable □ Sorviceable □ Sorviceable □ Sorviceable □ Sorviceable □ Shear installes	TRUSSES  WOOD FRAMING Unsafe/Wom/Neare  Missing framin oosts/beams overspanned/bea ed*/deteriorated*/sed	TONCRETE  CONCRETE  CONCRETE  TRUSS  Control (S) / block(s) (S)  Earth-to-wood coring poorly / twisting / stilled (E)  Its / shear panels (E)	by removal of floor confound on interior / exfound on interior / exfound on interior / exfound on interior / exfound on interior / exforces or settlement in all truttue meass. Floor coverings are untrumoved  NOT VISIBLE  Not fully visible of Moisture stains / contact ③	cterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure / water present* *
☐ Slab not visible due to ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ N/A  COMMENTS: ☐ Notice: All slabs experience some degrinspector will, at additional cost, reinspector will, at additional cost,	o carpet and floor of Uneven areas Uneven areas Serviceable  end cracking due to shrinkage in the stip provided the client removes to the conventional of the conventional of the stip period of the conventional of the convention in the convention is suspected to the convention in the convention is suspected to the convention in the convention is suspected to the convention in t	in flooring*  In flooring*  Vents blocked  TRUSSES  WOOD FRAMING  Unsafe/Worn/Neare  Missing framing  overspanned/bea  ed*/deteriorated*/sed  In No anchor bolded revealed: moist	shortcoverings prevent recognitions of the control	by removal of floor confound on interior / exfound on interior / exformed of cracks or settlement in all but the meass. Floor coverings are not removed on the coverings are not removed on the covering of the coveri	cterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure/water present* * mended ①
O Slab not visible due to Cracks found* Cracks found* NTILATION_N/A COMMENTS:  Notice: All stabs experience some degree inspector will, at additional cost, reinspector of the complex service able	o carpet and floor of Uneven areas Uneven areas Serviceable  end cracking due to shrinkage in the stip provided the client removes to the conventional of the conventional of the stip period of the conventional of the convention in the convention is suspected to the convention in the convention is suspected to the convention in the convention is suspected to the convention in t	to vering-recomment in flooring*  Vents blocked blocke	shortcoverings prevent recognitions of the control	by removal of floor confound on interior / exfound interior sets of the followings are not removed  NOT VISIBLE  Not fully visible  Not fully visible  Not fully visible  Contact © © P Deformation of the confound of the confo	exterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure / water present*  mended ① alled incorrectly*
O Slab not visible due to Cracks found* Cracks found* NTILATION_N/A COMMENTS:  Number of the Comments of the C	© Carpet and floor of Uneven areas  ☐ Uneven areas ☐ Serviceable  © Serviceable  © JOISTS  © CONVENTIONAL ☐ Not functional/ g framing ② unsecured piers / p / columns appear: pperly sloped*/ cracke ☐ Shear installed ioration is suspected  Mineral wool / Cellul	TRUSSES  Unsafe/Wom/Neare  Wood FRAMING Unsafe/Wom/Neare  Wissing framin oosts/beams  overspanned/bea ed*/deteriorated*/sed I No anchor booted revealed: moist usee/Vermiculite/Foan Unot installed*	TONCRETE  Concrete Control of Literary (1988)  Concrete Concrete Concrete Control of Literary (1988)  Control o	by removal of floor confound on interior / exfound interior of confound interior / exfound interi	cterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure / water present* * mended ① alled incorrectly*
☐ Slab not visible due to ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Comments: ☐ Matten: All stabs experience some degree inspector will, at additional cost, reinspector will, at additional cost, re	o carpet and floor of Uneven areas  Uneven areas  Serviceable  e of cracking due to simulage in the client removes to possible the client removes the control of the client removes th	in flooring*  I Vents blocked  TRUSSES  WOOD FRAMING Unsafe/Worn/Neare  Missing framinosts/beams ② overspanned/bea ed*/deteriorated*/sed I No anchor booked revealed: moist use/Vermiculite/Foam I Not installed* I Not functional*	stloor coverings prevent recognitions before from damage caused by this process of the country o	by removal of floor confound on interior / exfound interior of confound interior / exfound interi	cterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure / water present* * mended ① alled incorrectly*
☐ Slab not visible due to ☐ Cracks found* ☐ Cracks found* NTILATION N/A  COMMENTS:    Notice: All stabs experience some degree inspector will, at additional cost, reinspector will, at	o carpet and floor of Uneven areas  Uneven areas  Serviceable  e of cracking due to simulage in the client removes to possible the client removes the control of the client removes th	TRUSSES  Unsafe/Wom/Neare  Wood FRAMING Unsafe/Wom/Neare  Wissing framin oosts/beams  overspanned/bea ed*/deteriorated*/sed I No anchor booted revealed: moist usee/Vermiculite/Foan Unot installed*	TONCRETE  Concrete Control of Literary (1988)  Concrete Concrete Concrete Control of Literary (1988)  Control o	by removal of floor confound on interior / exfound interior of confound interior / exfound interi	cterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure / water present* * mended ① alled incorrectly*
☐ Slab not visible due to ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Comments: ☐ Motice: All status experience some degre inspector will, at additional cost, noinspector will, at additional cost, no	o carpet and floor of Uneven areas  Uneven areas  Serviceable  e of cracking due to simulage in the client removes to possible the client removes the control of the client removes th	in flooring*  I Vents blocked  TRUSSES  WOOD FRAMING Unsafe/Worn/Neare  Missing framinosts/beams ② overspanned/bea ed*/deteriorated*/sed I No anchor booked revealed: moist use/Vermiculite/Foam I Not installed* I Not functional*	TONCRETE  Concrete Control of Literary (1988)  Concrete Concrete Concrete Control of Literary (1988)  Control o	by removal of floor confound on interior / exfound interior of confound interior / exfound interi	cterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure / water present* * mended ① alled incorrectly*
☐ Slab not visible due to ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Comments: ☐ Notice: All stabs experience some degree inspector will, at additional cost, reinspector will, at additional cost, re	o carpet and floor of Uneven areas  Uneven areas  Serviceable  e of cracking due to simulage in the client removes to possible the client removes the control of the client removes th	in flooring*  I Vents blocked  TRUSSES  WOOD FRAMING Unsafe/Worn/Neare  Missing framinosts/beams ② overspanned/bea ed*/deteriorated*/sed I No anchor booked revealed: moist use/Vermiculite/Foam I Not installed* I Not functional*	TONCRETE  Concrete Control of Literary (1988)  Concrete Concrete Concrete Control of Literary (1988)  Control o	by removal of floor confound on interior / exfound interior of confound interior / exfound interi	cterior walls ① ← amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure / water present* * mended ① alled incorrectly*
☐ Slab not visible due to ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Comments: ☐ Notice: All stabs experience some degree inspector will, at additional cost, reinspector will, at additional cost, re	o carpet and floor of Uneven areas  □ Uneven areas □ Serviceable  end cracking due to shrinkage in the stip provided the client removes II  ◇ JOISTS ◇ CONVENTIONAL □ Not functional/ g framing ② unsecured piers / y / columns appear: pperly sloped*/cracke □ Shear installed ioration is suspected Mineral wool / Cellul □ Installed □ Serviceable	in flooring*  O Vents blocked  in flooring*  Vents blocked  in drying process, it most instance and concerning and releases the inspection of the concerning and releases the inspection.  TRUSSES  Unsafe/Worn/Near of Missing framing oosts / beams ②  overspanned / beams ②  overspanned / beams down overspanned / seams down on the concerning and releases / seams down on the concerning and the c	shortcaverings prevent recognitions of the control	by removal of floor confound on interior / exfound on interior sets.  If the coverings are not removed to NOT VISIBLE  Not fully visible on Not fully vi	exterior walls ① ← amaged / missing  outsevere cases. The during this inspection. *  * / damage ② ③ extris under house* sed / rotted ② ure / water present* * mended ① alled incorrectly* ed*
☐ Slab not visible due to ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Cracks found* ☐ Comments: ☐ Notice: All stabs experience some degree inspector will, at additional cost, reinspector will, at additional cost, re	O carpet and floor of Uneven areas  ☐ Uneven areas ☐ Serviceable  end cracking due to strinkage in test, provided the client removes I  ◇ JOISTS ◇ CONVENTIONAL ☐ Not functional/g framing ② unsecured piers / f / columns appear: pperly sloped* / crack ☐ Shear installed ioration is suspected. ☐ Installed ☐ Serviceable ☐ Serviceable	in flooring*  Vents blocked  TRUSSES  WOOD FRAMING  Unsafe/Worn/Neare  Missing framinosts/beams® overspanned/bea ed*/deteriorated*/sed D No anchor boled revealed: moist ose/Vermiculite/Foam Not installed* D Not functional*	TONCRETE  Concrete Control of Literary (1988)  Concrete Concrete Concrete Control of Literary (1988)  Control o	by removal of floor confound on interior / exfound in all authorizes. Floor coverings are untremoved  NOT VISIBLE  Not fully visible  Not fully visible  Not fully visible  Not fully visible  Footact ® P De  overnotched / crack  Bolts not visible  Engineer recompot visible / loose / installed  Sump pump need	amaged / missing  ostsevere cases. The during this inspection.*  * / damage ②③ ebris under house* ted / rotted ② ure / water present*  mended ① alled incorrectly* l incorrectly* ed*

ME7 RO	OF PARTY			
② Recomme	end evaluation by a structural/geo-technical or and evaluation and repairs by a licensed cont ualified termite report for further information	ractor 🕒 🖲 Upgrades an	safety hazard - correction is needed e recommended for safety enhancemen arrants attention/repair or monitoring	ıt
Roof style: How Inspected:	☐ Hip ☐ Gable☐ Walked ☐ Viewed from☐ Not fully visible due to:height		□ Mansard/Shed □ noculars (These inspections are limed by the debris are limed by the debris are limed by the limed by th	ited)*
O Location:	A ASPHALT / COMPOSITION SHINGLE	♦ WOOD SHAKE	♦ WOOD SHINGLE # OF LAYERS_	
Typical maintenance This maintenance Condition Few/many.damag Weathering / agin Loose / displaced/ Roof material app	ole / within useful life	air/replacement of damag of the building and be d agingregular mainte repair/replacement@ ☐ Holes / opening ☐ Pitch appears ir ☐ Exposed / lifted	red/missing ridge and other shakes/shir performed on a regular basis.* enance and inspection advised.* • Moisture damaged / moss coviss / exposed / deteriorated membra	ngles. ered@ ine@
20 Location:	CLAY/CONCRETE/FIBROUSTILE	♦ SLATE / METAL	♦ FIBERGLASS PANEL ♦	
☐ Cracked / broken / ☐ Loose / displaced /	ble / within useful life	ed/missing fasteners@ ②   ☐ Holes/opening	☐ Dented/rusted/deteriorated p	aint② ine②
Notice: Roots of this materia	ol are not walked to avoid causing damage. Not all tiles/	slates/pane)s are checked for atta	chment,* Inspection is limited,*	
21 Location:	A SUILT-UP ROOF: ROCK / CAP SHEET _	🔷 SINGLE-PLY/MODI	FIED BITUMEN/FOAM 🔷 ROLLCOMP	OSITION
☐ Typical maintena aggregate materia ☐ Excessive damage ☐ Blistering / cracki ☐ Evidence of pond ☐ Roof appears to b	ng/alligatoring*	ists of covering exposed nings, deteriorated roof al appears to be improp d surface ②	I/bare area with additional coating coverings, etc.* perly installed@  Open seams @ Moss cov Exposed fasteners@	g/
Roof Notes	NOTICE: Roof is part of Home	e Owners' Association:	Not inspected at this time.	
Notice: The report is an as to whether the roof h	opinion of the general quality and condition of the as leaked in the past, leaks now, or may be subject	realing.* The inspector canno to future leakage. This report is	t, and does not, offer an opinion or warranty issued in consideration of the foregoing discla	imer.*
☐ Vent caps appea ☐ Damaged flashin ☐ Skylight(s) appea	Flashings appear serviceable  proper flashing at: Roof/wall/edge/s serviceable	skylight / chimney / ven *	t ninec*	
·				
	sence of asbestos or other bazarnous materials is beyond the umigation may cause damage to roofs recommend reinspe 7 - 2004 ( T.E. OCHRODIUM OR OTHER PATION OF THIS REPO			

PAGES PLUMBING F
** This item is a safety hazard - correction is needed  ** Recommend evaluation by a structural/geo-technical engineer*  ** Recommend evaluation and repairs by a licensed contractor    ** Upgrades are recommended for safety enhancement    ** This item warrants attention/repair or monitoring
23 Main Line N/A COPPER / OALVANIZED / PLASTIC ine Bolice below) / JEAD (see "Indice below) CANNOT DETERMINE SIZE: 3/24 PRESSURE: OPSI @ S. AM / PM Above 80psi—adjustment / repair / install regulator @
☐ Appears serviceable ☐ Not functional / Unsafe / Worn / Near end of lifespan* ☐ Not fully visible: ☐ Main valve location: ☐ Not located* ☐ Operational ☐ Not operational ☐ Valve not tested* ☐ Copper not protected from concrete* ☐ Water softener installed - (water condition/quality is not tested*) ☐ Leaks at water conditioner@
24 Supply Lines (N/A) & COPPER/GALVANIZED/PLASTIC (see "Notice" below) / LEAD (see "Notice" below)
Appear serviceable
COMMENTS:  Notice: Underground pipes or pipes inside walls cannot be judged for sizing, leaks or corrosion.* Water quality testing or tasting for hazards such as lead is not part of this inspection.*  Notice: Be advised that some "Polybutylene" plastic piping systems have experienced documented problems. Contact the manufacturer or an expert for turther information and evaluations.*
25 Waste Lines ON/A CAST IRON / GALVANIZED / COPPER / LEAD / PLASTIC (see Notice below) CANNOT DETERMINE COMMITTEE OF THE COM
□ Appear serviceable □ Not functional / Unsafe / Worn / Near end of lifespan* □ Not fully visible: □ Minor corrosion* ☑ Moderate / major rust / corrosion® □ Pipes lack proper support® □ Leaks ② □ Insufficient fall for adequate drainage② □ Open waste / sewer line②④ □ Improper / no visible trap / vent ② □ Plumbing vents/traps appear serviceable (however all vents/traps are not fully visible) □ Vent missing / terminates improperly② □ COMMENTS: □ Vent missing / terminates improperly②
Notice: City sewor zervice, septic systems and all anderground pipes are out a part of this inspection. Future drainage performance is also not determined.* Notice: Be advised that some "ABS" plastic piping systems have experienced documented problems. Contact the manuacturer or plumbing expert for further information and evaluations.*
26 Fuel System System SHUT VALVE LOCATION: Fuel system is not on for inspection - suggest utilities company light and test appliances."
□ Appears serviceable □ Not functional / Unsafe / Worn / Near end of lifespan*       □ Not fully visible:
COMMENTS:
27 Water Heater(s) N/A COCATION UNIT A: UNIT B: UNIT B: UNIT C: UNIT C
□ Appears serviceable □ Not functional / Unsafe / Worn / Near end of lifespan* □ Pilot / system off—could not inspect* □ Rust flakes in burner chamber* □ Burner flame appears improper ② □ Heater leaks: water / gas / oil ② ⑥  p Water shutoff valve installed (no test) □ Valve missing / broken / leaks ② □ Rust / corrosion on pipes / valve / tank* □ TPR valve installed on tank(s) □ No TPR valve installed ② □ PR valve on piping system only② □ TPR pipe: improper type / reduced ② □ TPR pipe: missing / short / threaded / capped / reduced / unsafe termination ②  © Combustion air is available □ N/A □ Air supply blocked / none provided ② □ No gas line drip leg* □ Vent flue piping is serviceable □ N/A □ Pipe damaged / disconnected ② □ Improper / loose / missing vent ②
☐ Vent flue backdrafting noted ② ☐ Vent rise / angle is improper.② ☐ Elbows of 90 / multiple 60 degrees ② ☐ Insufficient clearance to combustible material ③ ☐ Gas heater flame in garage is not 18" above floor ② ⑥ ☐ Improper straps *⑤ ☐ Improper straps *⑥
☐ Thermal blanket serviceableN/A ☐ Blanket damaged / loose* ☐ Blanket needed* ☐ Missing a catch pan with an exterior routed drain line* ☐ Recommend protecting heater from physical damage* ☐ Enclosure / door missing / damaged* ☐ Improper firewall ②  COMMENTS:
Notice: Estimate of remaining life is not part of this inspection. Solar systems are not part of this inspection. Hot water reclicateding pumps/systems are not part of this inspection.*  **Septemble** 1997 - 2004 L.T.A. REPRODUCTION OR UTILIZATION OF THIS REPORT WITHOUT WRITTEN AUTHORIZATION BY L.T.A. IS NOT PERMITTED 0X2HFX0801

### © Upgrades are recommended for safety enhancement ② Recommend evaluation and repairs by a licensed contractor ® Refer to qualified termite report for further information \* This item warrants attention/repair or monitoring 28 Description Approximate BTU's Unit A n/a Unit B n/aLocation A Location B Location C Heating Type: Heating Type: Heating Type: Q Forced air Q Boiler/steam ☐ Forced air ☐ Boiler / steam \*\*Forced air ☐ Boiler/steam ☐ Floor/wall/gravity ☐ Radiant ☐ Floor wall Lefav ☐ Radiant ☐ Floor/wall/grav ☐ Radiant ☐ Heat Pump ☐ Heat Pump Q Heat Pump Fuel Type: Fuel Type: Fuel Type: Matural gas ☐ Natural gas ☐ Natural gas Oil Q Oil **E**lectric ☐ Electric ☐ Coal/wood Coal/wood ☐ Electric ☐ Coal/wood ☐ Propane ☐ Propane Propane Molice: If a fuel burning heater / furnace is located in a bedroom, we recommend evaluation by a qualified heating contractor for safety and air volume requirements. ☐ Pilot not on / utilities off / electric ignition malfunction - could not inspect\* Unit: A B C 29 Condition Unit: A B C Did not respond to normal controls @ ☐ System(s) appear serviceable Unit: A B C ☐ Not functional / Unsafe / Worn / Near end of lifespan / Damage / Deterioration / Defects\* @\_\_\_ Unit: A B C ☐ System does not appear to have been serviced per manufacturer's instructions, within the last year\* \*Unit: A B C COMMENTS: \_ Notice: Inspector does not light pilots. If pilots are "OFF", a full inspection is not possible. It is suggested that heating systems be activated and fully inspected PRIOR TO CLOSE OF TRANSACTION. 30 Venting Unit: A B C ☑ Unable to fully inspect vent pipe\* D Backventing @ Unit: A B C ☐ Damage / deterioration / defects\* Unit: A B C ☐ Appears serviceable Unit: A B C ☐ Vent lacks clearance from combustible ②④ Unit: A B C ☐ Improper vent rise / elbow angle ② Unit: A B C ☐ Improper materials used for vent pipe ②④ Unit: A B C ☐ Soot/rust on vent pipe/chamber ② Unit: A B C ☐ Vent terminates near window / opening ② ● Unit: A B C ☐ Defective barometric / vent damper / induced draft fan ② COMMENTS: 31 Combustion Air 🚜 🗀 Air supply blocked\* Unit: A B C ☐ No/inadequate air supply ② ④ Unit: A B C Appears serviceable Unit: A-B C ☐ Damage / deterioration / defects\* Unit: A B C ☐ Combustion and return air sources are too close or mixing ② ● Unit: A B C ☐ Recommend sealing platform at heater base / holes in platform\* Unit: A B C COMMENTS: 32 Burners ☐ Closed system / unable to inspect\* ☐ Unusual flame pattern ②④ Unit: A B C ☐ Burner flame appears typical Unit: A B C Damaged chamber / refractory @@ Unit: A B C ☐ Rust flakes / oil stains in burn chamber ② Unit: A B C ☐ Soot / charring in burn chamber ② Unit: A B C COMMENTS:

33 Distribution □ Ducts/REGISTERS □ PIPES/CONVECTORS □ PIPES/RADIATORS □ ELECTRIC/BASEBOARD
□ Ducts: Damaged / crushed / disconnected / holes / openings / leak ② Unit: A B C
□ Damaged / missing register(s)\* Unit: A B C □ Insulation damaged / missing\*
□ Zone valve did not operate② Unit: A B C □ Circulating pump - leaks / noisy / inoperative ② Unit: A B C
□ Radiator / convector / fitting: Leaks / corroded / rusted / cold / damaged / inoperative ② Unit: A B C
□ COMMENTS:

Notice: The inspector is not equipped to thoroughly inspect heat exchangers for evidence of cracks or holes, as this can only be done by dismantling the unit or other technical procedures. This is beyond the scope of this inspection.\* Some turnaces are designed in such a way that inspection is almost impossible.\* Safety devices are not tested by this company.\*

Notice: Asbestos materials have been commonity used in heating systems.\* Determining the presence of asbestos can ONLY be performed by laboratory testing and is beyond the scope of this inspection.\*
Notice: It is suggested that all homes with tirel burning heating systems have a carbon manoxide detector installed for added asfety.\*

1997 - 2004 L.T.A. REPRODUCTION OR UTILIZATION OF THIS REPORT WITHOUT WRITTEN AUTHORIZATION BY L.T.A. IS NOT PERMITTED

PAGE 10 HEAT 2/COOLING
** This item is a safety hazard - correction is needed  ** Recommend evaluation and repairs by a licensed contractor  ** Refer to qualified termite report for further information  ** This item is a safety hazard - correction is needed  ** Upgrades are recommended for safety enhancement  ** This item warrants attention/repair or monitoring
34 Normal Controls  Unit: A B C Unit: A B C Damage / deterioration / defects* Unit: A B C Controls / gauges need repair / replacement  Unit: A B C Unit: A B C Expansion tank - rusted / leaks / water logged  COMMENTS:
Notice: Thermostats are not checked for calibration or timed functions.* Adequacy, efficiency or even heat distribution of the system through the house is not part of this inspection.*
35 Air Filters Appear serviceable
36 Heating Notes NA Recommend complete system evaluation Unable to locate heat in all rooms*  Suggest cleaning & servicing blower/motor/pilot/vent system/burners/boiler/pump
Notice: Varification of fine location or condition of underground fuel sterage tanks is not part of this inspection.* Environmental risks, if any, are also not included.* Notice: Asbestos materials have been commonly used in healing systems.* Determining the presence of asbestos can ONLY be performed by laboratory testing and is beyond the scope of this inspection.*  37 Evaporative Cooler (AV) LOCATION(S): UNIT A UNIT B Q 120 VOLT 240 VOLT
□ Appears serviceable □ Not functional / Unsafe / Worn / Near end of lifespan* □ Not fully visible: □ Unit makes an unusual noise ② □ Unit is not level* □ Flashing is missing / improper* □ Pads are damaged* □ Unit rusted / corroded / leaks* □ Float valve / pump not functioning* □ Leaking noted* □ No electrical disconnect provided at unit ② □ Improper / deteriorated / no conduit / roof flashing ② □ Proper grounding not provided at unit ③ □ Unit rusted / no conduit / roof flashing ② □ Proper grounding not provided at unit ③ □ Unit rusted / no conduit / roof flashing ② □ Proper grounding not provided at unit ③ □ Unit is not level* □ Flashing is missing / improper* □ Unit is not level* □ Flashing is missing / improper* □ Unit is not level* □ Flashing is missing / improper* □ Leaking noted* □ Unit is not level* □ Flashing is missing / improper* □ Leaking noted* □ Unit rusted / corroded / leaks* □ Improper / deteriorated / no conduit / roof flashing ② □ Proper grounding not provided at unit ③ □ Unit rusted / corroded / leaks* □ Improper / deteriorated / no conduit / roof flashing ② □ Proper grounding not provided at unit ③ □ Unit rusted / corroded / leaks* □ Improper / deteriorated / no conduit / roof flashing ② □ Proper grounding not provided at unit ③ □ Unit rusted / corroded / leaks* □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □ Improper / deteriorated / no conduit / roof flashing ③ □
38 Air Conditioning (NA) LOCATION(S): UNIT A UNIT B UNIT C
♦ SPLIT SYSTEM / PACKAGE UNIT / WALL / WINDOW UNIT       ♦ HEAT PUMP - AIR / GROUND / WATER SOURCE       ♦ Unable to inspect / test*         □ Appears serviceable       UNIT: A B C       □ Not functional / Unsafe / Worn / Near end of lifespan*       UNIT: A B C         □ Air temp below 65% Fahrenheit: Unable to test system(s)* (operation could cause damage)       □ One speed fan only*       UNIT: A B C         □ Not level / makes unusual noise       UNIT: A B C       □ Temperature differential is incorrect       ② UNIT: A B C         □ Condenser coil: damaged / poor air circulation       UNIT: A B C       □ Recommend system service*       ② UNIT: A B C
POWER:
CONDENSATE:N/A
REFRIGERANT LINES:N/A
COMMENTS:
DATA PLATE: Notice: The inspector does not perform pressure tests on cociant systems; therefore no representation is made regarding coclanic harpe or line integrity. Notice: Subjective judgment of system capacity is not part of the inspection. Window or portable units are not inspected.  Counter: © 1997 - 2004 (.T.A., REPRODUCTION OR UTILIZATION OF THIS REPORT WITHOUT WRITTEN AUTHORIZATION BY L.T.A. IS NOT PERMITTED CX2HFX1001 10

② Recommend eva	aluation and repai	tural/geo-technical engin rs by a licensed contracto r further information	r (5) l	Jpgrades are r	afety hazard - correction i ecommended for safety e ants attention/repair or m	nhancement
Service . NA	OVERHEAD 120V*	♦ UNDERGROUND ♦ 240V / 120V	•	MBER OF CON	DUCTORS AMPS NOT DETERMI	YED
Appears serviceable Loose / damaged conne Conductors too close to Ground present Main disconnectinspecto OMMENTS:	ections / flashing o ground / drive G Ground loose	/ roof / pool@@ / disconnected at: @@	W D C	res: Frayed, res touch tre	'improper splices / tap es* Contact utility co	on main wires mpany*@ estem not visible
Notice: Six or fewer breakers Notice: If the service ampera	usually do not require ge is less than 180, u	a main breaker, however this t prade may be needed to opera	may indica te larger e	te light electrical lectrical applianc	capacity.*	\$7-78 <b>4</b> 4440,\$7466.#\$
Main Panel N/A  Appears serviceable		at main / no inspectio terioration / Unsafe / No	*		Panel rating nmend further evaluat O Not accessible*	ion*
DMMENTS:	антумдестна электиция финер чести 200 година 100 година 100 година 100 година 100 година 100 година 100 година			A CONTRACTOR OF THE PROPERTY O		Description of the second of t
Conductors N/A	SERVICE WIRE:	♦ COPPER		MINIM	CANNOT DETERMINE	•
of the second se	BRANCH WIRE	COPPER  DATE OF THE CARDINE	*	IMINUM OD AND TUDE	A AUTEN / PLASTIC CON	` >≤ 15T
		5: p NON-METALLIC CABLE			♦ METAL / PLASTIC CON	All
Sub-panels N/A		is locked/inaccessibl		and the second second		idod#
Panel Notes		T PROTECTION DEVICES IN:		THURNISPECT	SREAKERS / FUSES	·
Improper wiring at panel Two wires on one non-rat Overfusing (fuse / breake Direct tap - wires not pro Aluminum wiring noted a uninum connections should be check Missing bushing / clamp Breakers / fuses: damaged Electrical system appears COMMENTS:	ted breaker at pan r size too large for tected by fuse/bre at the general 120 ed by alicensed electricia on wire(s) at pane / inoperable / not li	wire) panel #	Science Science Science New Part Part Part Part Part Part Part Part	orching / melti outral and grou nel bond is no tioxidant not v oprotected ope ssing 240 volt - pening(s) / miss sed neutral wird	nanel #* Hang / rust / corrosion at pand wires connected at substituted for safety at parisible on aluminum wires ing(s) in panel # handle tie(s) at panel # sing deadfront cover(s) a panel #	nel #
Wiring Notes N/A	Cl Sample of fi	xtures, switches and out	lets teste	d appear serv	ceable D Furnish	ings prevent testi atlets and switche
Polarity and grounding of Three prong outlets did n			es, in the	garage and or	the exterior appear ser	/iceable 2x
Reverse polarity at:		24	☐ Ev	idence of over	heating/arcing at:	2)
Outlet not operational at	endi audiata I audia			sht/fan not op	erational/ungrounded a	t:*
Loose / damaged / miswi Not exterior rated wire /	red: oddets / switt pox / cover at:		M D Ex	tension cord in	sed as wiring at:	
Exposed wiring needs pr	otection at:	24		oen Neutral at		(2)
Improper wiring at: 24	Garage / atti	c 🔘 Kitchen/exterior	CA Cr	audenaco	Rasement	
Exposed splices at: 24 Box cover missing at:*	"Li Garage/atti	ic L Kitchen/exterior		awispace	Basement Basement	
'GFCI'(s) responded to t			ים מי 🔲	awispace FCI' not opera	tional at:	<u> </u>
'GFCI', (a safety device to						
Doorbell worked / none	☐ Not operation	onal ②	☐ Fix	ture is unsafe / c	orroded / missing / damaged	·
Doginen Marked   none	- 1					

Recommend evaluation Recommend evaluation Refer to qualified to	ation by a structural/g ation and repairs by a ermite report for furth	licensed contractor	<li>⑤ Upgrades are n</li>	afety hazard - correctio ecommended for safet ants attention/repair or	y enhancement
Doors (Entry) NA A Hardware operational O	Appear serviceak Weather stripping Not operational*		□ Damage / deteri □ Damaged* -	oration/defects*/  D No weather stri  D Damaged door	pping* jamb*
Doors (Int.) NA P	quare - may indica	te movement®	<ul><li>□ Need adjustment/</li><li>□ Not operational</li><li>□ Door(s) rub/stice</li></ul>	/missing/loose*_	
	Alantamen Action (Color of the Color of the	No. of the control of		annia de la maria de 1940 de 1960 de la contración de la contracta de la contr	мерения при на поднечения на при на
I Latching hardware is or	Not tempered@© Carational	Unable to deten  Not operational	I/in need of adjustn mine if glass is temp * t checked*	pered*	
COMMENTS:					_
Windows NA &	ALUMINUM () SLIDING. ()	> WOOD	♦ VINYL/METAL ♦ DOUBLEHUNG	♦ DUAL PANE	♦ SECURITY BARS
<b>Sample tested appear se</b> Broken sash cords*  Caulking/glazing deterio	erviceable Difficult to opera	te / slide*	U:*	☐ Won't lock / ope	n/close*
					t tested*
3 Screens not checked G	Few/many dama	ged/missing*	☐ Security bars nor	n-openable 🎱 / no	t tested*
A Screens not checked	Few/many dama	ged/missing*	Security bars nor	n-openable @@ / no	t tested*
OMMENTS:  Notice: Determining condition of aff the Interior Walls	rmopane windows is not pass  DRYWALL	ged/missing*  interducto temperature, wea	Security bars not there and lighting variations. Ch	n-openable 23. / no  cck with owner for further inform  WALLPAPER	t tested*
OMMENTS:  Notice: Determining condition of all the interior Walls NA   General condition appear  No cracks found Furnishings prevent full in	rmopane windows is not pass  DRYWALL	ged/missing*  interducto temperature, wea	Security bars not there and lighting variations. Ch	n-openable 23. / no  cck with owner for further inform  WALLPAPER	t tested*
OMMENTS:  Notice: Determining condition of all the interior Walls NA   General condition appear  No cracks found Furnishings prevent full in	rmopane windows is not pass  DRYWALL  Ars serviceable  Common cracks  nspection - do a care	interneto temperature, wea  PLASTER  Needs repair*  Major cracks@ eful check on your	Security bars not there and lighting variations. Ch	n-openable 23. / no  cck with owner for further inform  WALLPAPER	t tested*
OMMENTS:  Notice: Determining condition of all the interior Walls  OGeneral condition appear No cracks found Furnishings prevent full interior walls in the comments:  Notice: The condition of walls behind we consider the condition of walls behind we condition of walls are condition.	rmopane windows is not pass  DRYWALL  Ars serviceable  Common cracks  nspection - do a car-	interneto temperature, wea  PLASTER  Needs repair*  Major cracks@ eful check on your	Cl Security bars nor ther and lighting variations. Ch  PANELING  Moist/dry - sta  Nail pops* final walkthrough*	n-openable 23. / no  cck with owner for further inform  WALLPAPER	t tested*
OMMENTS:  Notice: Determining condition of aff the interior Walls  OGeneral condition appear of the condition of aff the interior Walls  OGeneral condition appear of the condition of walls behind we condition of walls behind we condition appear of the condition appear o	rmopane windows is not pass  DRYWALL  Ars serviceable  Common cracks  Inspection - do a care  allpaper, paneling and turnis  DRYWALL  Ars serviceable	inte due to temperature, wea  PLASTER  Needs repair* Major cracks@ eful check on your  ings cannot be judged.  ACOUSTIC SPRAY Moist* @	☐ Security bars nor  ther and lighting variations. Th  PANELING  Moist/dry - sta  Nail pops* final walkthrough*  CEILING TILE	n-openable @ / no  cck with owner for terther inform  WALLPAPER  ins / damage*  Holes / openings, Recommend revi  PLASTER  Ceiling height a	/exposed frame* iew by engineer ①  wood /BEAM appears low* mine*
Notice: Determining condition of aff the interior Walls  General condition appear No cracks found Furnishings prevent full incomments:  Notice: The condition of walls behind	rmopane windows is not pass  DRYWALL  Ars serviceable Common cracks  allpaper, paneling and turnis  DRYWALL  Ars serviceable Common cracks  Common cracks	ible due to temperature, wea  PLASTER  Needs repair* Major cracks@ eful check on your  hings cannot be judged.  ACOUSTIC SPRAY  Damaged* Moist* @  Major cracks*_	☐ Security bars nor hiter and lighting variations. Ch  PANELING  Moist/dry - sta  Nail pops* final walkthrough*  CEILING TILE  Dry*	n-openable @ / no  watth owner for turther inform  PLASTER  Ceiling height a  Unable to deter  Recommend eva	/exposed frame* ew by engineer ①  wood /BEAM appears low* mine* luation by engineer ①
OMMENTS:  Notice: Determining condition of all the interior Walls NA   General condition appear  Notice: The condition of walls behind was  Ceilings NA   General condition appear  Notice: The condition of walls behind was  Ceilings NA   Comments:  Notice: Determining whether acoustic special conditions appear  COMMENTS:	rmopane windows is not poss  DRYWALL  Ars serviceable  Common cracks  DRYWALL  Alpaper, paneling and turnis  DRYWALL  Ars serviceable  Common cracks  Common cracks	ible due to temperature, wea  PLASTER  Needs repair* Major cracks@ eful check on your  hings cannot be judged.  ACOUSTIC SPRAY  Damaged* Moist* @  Major cracks*_	CI Security bars nor ther and lighting variations. Ch  PANELING  Moist/dry - sta  Nail pops* final walkthrough*  CEILING TILE  Dry*	n-openable @ / no  neck with owner for further inform  WALLPAPER  ins / damage*  Holes / openings,  Recommend revi  PLASTER  Ceiling height a  Unable to deter  Recommend eva	/exposed frame* ew by engineer ①  wood /BEAM appears low* mine* luation by engineer ①
OMMENTS:  Notice: Determining condition of all the Interior Walls NA   General condition appear No cracks found Furnishings prevent full incomments:  Notice: The condition of walls behind	rmopane windows is not pass  DRYWALL  Ars serviceable Common cracks  DRYWALL  Attraction - do a care  allpaper, paneling and turnis  DRYWALL  Ars serviceable  Common cracks  CARPET	intermental intermediate in the first to temperature, weather the first the	☐ Security bars nor  ther and lighting variations. Th  PANELING  Moist/dry - sta  Nail pops* final walkthrough*  CEILING TILE  Dry*  Inspection. For information con  WOOD  ioration* iile/carpet damaged	n-openable @ / no  n-openable @ / no  n-openable @ / no  neck with owner for turther inform  water water water water water water  ins / damage*  Holes / openings, Recommend revi  PLASTER  Ceiling height a  Unable to deter Recommend eva	t tested*  /exposed frame*  ew by engineer ①  wood /BEAM  appears low* mine* luation by engineer ①  floor*

PAGE 13 INTERIOR 2	
KEY: ① Recommend evaluation by a structu ② Recommend evaluation and repairs ③ Refer to qualified termite report for f	by a licensed contractor S Upgrades are recommended for safety enhancement
52 Fireplace(s) (A) O LOCATION(S)	♦ A
☐ Appears serviceable UNIT A B C ☐ Deteriorated mortar* UNIT A B C ☐ Gas operational N/A UNIT A B C ☐ Improper gas piping ②④ UNIT A B C ☐ Damper operational UNIT A B C	☐ Gas is inoperative ② UNIT A B C ☐ Gas capped - no test* UNIT A B C ☐ Flue needs cleaning② UNIT A B C ☐ UNIT A B C ☐ UNIT A B C ☐ Flue needs cleaning② UNIT A B C
Maine: Recommond inclulions estate opener as designer when are	logs are present. * Wood and astres are not moved for inspection. Recommend clearing debris and further evaluation.
53 Interior features (A)   Central vacuum	
☐ Ceiling fan(s) is (are) operational ☐ Intercom system not part of this inspection* ☐ Interior stairs appear serviceable ☐ Stair handrail appears serviceable ☐ Wet bar faucet appears serviceable ☐ Counter appears serviceable ☐ Plumbing under sink serviceable ☐ COMMENTS:	☐ Fan is non-operational / vibrates / wobbles / improperly supported ② ☐ Security system is not part of this inspection* ☐ Uneven rise / run on steps ③④ ☐ Stairway is too narrow / steep ③④ ☐ Railing is loose / improper / missing* ☐ Openings in rails are too wide ④⑤ ☐ Faucet is not operational ⑨ ☐ Faucet leaks ◎ ☐ Cold water onl ☐ Damage / deterioration to counter / cabinet* ☐ Icemaker not on ☐ Leaks ② ☐ Improper piping ③
54 Smoke Detector  □  □ Indicator light on □  □ Test button responds □ Did not respond comments:	
55 Laundry (A) 🗘 GARAGE	♦ BASEMENT ♦ SERVICE AREA
☐ Piping (water & waste) serviceable ☐ Electrical outlet grounded (120 volt) ☐ 240 volt outlet operationalN/A ☐ Gas piping appears serviceableN/A ☐ Dryer venting provided	Unable to view / not tested* Unable to test* □ Ungrounded* Unable to test* □ Ungrounded* Unoperative* □ No 240 outlet Unoperative* □ No 240 outlet Unoperative* □ No 240 outlet Unoperative* □ No / improper gas valve / line ② Unoperative □ Dryer venting not provided* Unoperative □ No / improper gas valve / line ② Unoperative □ Dryer vents into attic / crawlspace*
☐ Laundry sink serviceable N/A☐ Plumbing below sink serviceable☐ Faucet operational COMMENTS:	☐ Damage / deterioration to sink* ☐ Sink is loose / slow draining* ☐ Corrosion / deterioration* ☐ Improper piping ② ☐ Leaks ② ☐ Hot/cold reversed ③
Nutice: Washing machines and dryers are not tested or moved duri	ing this inspection condition of walls or thooring under cannot be judged. The inspector does not test ned may be subject to leaking.
Stalling till parta  Roof frame:	♦ TRUSS ♦ RAFTER FRAMING X ACCESS LOCATION
CEILING FRAME:  How Inspected:	↑ TRUSS ↑ JOIST FRAMING X Inspection limited to view from access*  / Unsafe / Worn / Near end of lifespan*
Approximate depth: inches  Air/vapor retarder presentN/A  comments:	□ No insulation* □ Poor coverage* □ Compressed* □ Wrong side up insulation covers Knob & Tube wiring / lights / vents ② □ Air/vapor retarder not visible*
	us materials is beyond the scope of this inspection."  ofs — recommend reinspection for damage after tenting is completed, "  FILIZATION OF THIS REPORT WITHOUT WRITTEN AUTHORIZATION BY L.T.A. IS NOT PERMITTED 0X2HFX1361

13)

	② Recommend	l evaluation and	structural/geo-technical e repairs by a licensed contu ort for further-information	nginee actor	<ul><li>⑤ Upgrades</li></ul>	is a safety hazard - co are recommended fo warrants attention/re	r safety enhancement
GARAGE/C	ARPORT	♦ ATTACHED	( DETACHED	<b>\(\sigma\)</b>	CARPORT	·	
Floor		☐ Not fully v	risible*		Possible flamn	nable material on flo	or @
Appear No crac comments:	ks fóund	□ Damage / € Common c	deterioration / defects* cracks Q Major cracks		Floor raised / s	settled*	Q Poor drainage*
Walls/Ce		D Not fully vi	sible* Q Wall/ceiling	/ attic	access cover	/ladder does not a	appear fire rated ®
I Framing:	s serviceable Sagging / bowe	Moisture steed / damaged / alt	ains / damage on: ceilin ered @ 🚨 Exterior walls	g /wa s / soffi	/floor/post t/facia/trim	* D Holes / dam : damaged / deteri	age / missing covering* orated @
Ventila:	iion NA	☐ Appears serv	iceable S. Blacked / non	e* C	Window / sc	reens: damaged/i	noperative*
SIGNAL PROPERTY OF THE PARTY OF	ing Space 🖳	SOLID	♦ RATED DOOR	Ø	HOLLOW COR	E (NON-FIRE RESISTIV	E)* Ø
	operationalN/A						h / seal / enters bedroom*@ threshold / weatherstrip*
Exterior	Door HA	Q'Appears s	erviceable	ď	Damaged/d	elaminated*	U Needs adjustment
D Lock in	operative*	☐ Jamb / thr	eshold: damaged*		Not tested / I	olocked / locked / r	rubs jamb*
Vehicle		♦ ROLL UP	♦ TILT-UP	<b>\( \)</b>	SLIDING	♦. SWINGING	\$
Tension Safety s	rs serviceable n rods loose* orings installed e door(s) are lo	☐ Door war	deterioration / defects ped* Door needs a type springs* @® not test*	adjustn	nent / balancir Broken sprin	: Moisture stained / ng* 🗓 Hinges loos gs / safety wire @@ ks damaged @	
COMMENTS;			· · · · · · · · · · · · · · · · · · ·		-		
Automatic	Opener A	] □ Appears s	erviceable- # of units_		Non-operation	nal* Opener / au	to-reversé was not tested
] Autom	atic reverse o	Unit is disperated				djustment / lubrica DS 🔲 Electronic sens	tion* or: none / not functional*®&®
COMMENTS:		☐ Appears s	serviceable	Q	Damage / de	terioration / defect	s* Q Not fully visible
Improp Open s Outlets	er wiring@@ plices @@ s serviceable outlet(s) are in	U Junction b	viring subject to damage* poxes missing covers*@ pund / Reverse polarity @ ☐ Outlet(s) not	0 04	'GFCI' recoi		
I Some c					· · · · · · · · · · · · · · · · · · ·	-	
П Some с сомментs:		·	TO BE A STRUCTURE OF THE STRUCTURE AND A STRUCTURE OF THE				V

AGE 15 KITCHEN			
KEY: *** ① Recommend evaluation by a struct ② Recommend evaluation and repair ③ Refer to qualified termite report for	rs by a licensed contracti	or 🔞 Upgrades ar	a safety hazard - correction is needed re recommended for safety enhancement arrants attention/repair or monitoring
66 Kitchen Sink(s) 📈 □ Dishes block a	ccèss to sink, could n	ot inspect*	☐ Hot & cold water reversed*
Sink(s) appear(s) serviceable  Recommend sealing at sink to counter co		☐ Heavy wear/cl	hipped*
Faucet serviceable 🚨 Non-operation	nal / defective @ Pipes are rusted / co		irips / is corroded*
			ceable condition
	cess to sink and disposal	, could not inspect*	No inspection (power off)*.
Appear serviceable	/Unsafe/Worn/Nea  Unit makes unusung noted@@	nr end of lifespan* Ial noise* Loose/missing	<ul> <li>Not fully visible*  Interior corroded*</li> <li>Splash guard damaged / missing*</li> </ul>
		♦ COMBINATION ☐ Ranges/ cookto	
☐ Appear serviceable ☐ Not functional ☐ Upper / lower - right / left - front / rear: e	/ Unsafe / Worn / Nea lement / burner not fu Damage noted* Not applicable Burner did not op Gas valve is not v	r end of lifespan* unctional* Door does not Damaged gasket* perate @	☐ No inspection (power/gas off)* ☐ Heavy corrosion/wear* close properly* ☐ Cracked glass @
Notice: Salf-and/or continuous cleaning operations, clocks, ti			CONTROL OF THE PROPERTY OF THE
☐ Appear serviceable ☐ Not functiona		ar end of lifespan*	☐ No test (power / water off)* ☐ Not fully visible:
☐ Condition (door, liner, racks) serviceable☐ Soap dish inoperative*☐ Door seals appear serviceable	<ul><li> Rust / damage at:</li><li> Washer arm appe</li><li> Deteriorated*</li></ul>	ears frozen ②	Unit is not secured to cabinets*  Door won't close/open properly*
DRAIN LINE INSTALLATION:  Leaking noted at drain lines*	Cl Air gap device Cl No/improper air	☐ Hi-loop method	☐ Drain line is improperly installed ② ☐ Leaking noted at air gap device*
COMMENTS:	of distance beautiful and as 45-5.	Deposition #	
Notice: Determining adequacy of washing and drying functions  1 Special Features NA Special features	managar matar process and the process of the control of the contro		Heldtreichte der der Herberteilsche der der der der der der der der der de
☐ Trash compactor appears serviceable ☐ Microwave appears serviceable ☐ Water purifier installed - not inspected* ☐ Other features / appliances present but i	□ Non-operational □ Non-operational □ Instant hot water	② maker installed - no	☐ Compactor not inspected* / no key☐ Microwave not inspected* ot inspected*
COMMENTS:			
Notice: Refrigerators, treezers and built-in ice makers are		ITHOUT WRITTEN AUTHORIZAT	ION BY I.T.A. IS NOT PERMITTED 0X2HFX1501

AUL D BATHROOM								
© KEY : ① Recommend evaluation by a structural/geo-technical engineer ② Recommend evaluation and repairs by a licensed contractor ③ Upgrades are recommended for safety enhancement * This item warrants attention/repair or monitoring								
LOCATION: Bath A Bat	h B.				Bath CBath D			
72 Toilet  NA  Appears serviceable Toilet loose at floor* Recommend new wax seal / caulking at base* Water runs continually in tank* Does not flush properly*  COMMENTS:					Corrosion / leaking supply line*			
73 Sink  NA) Appears serviceable  Sink cracked / damaged*  Faucet appears serviceable  Sink faucet leaks* Low water volume *					Hot & cold water reversed*			
Drain appears serviceable Slow draining* Rust / corroded drain line * Leaking drain line @ Counter & Cabinet appear serviceable		الم			Drain stopper non-functional / missing*			
Damage / deterioration to counter* Grout / caulking needed at counter* COMMENTS:					Damage / deterioration to cabinet*			
74 Vent/Heat Appears serviceable Exhaust fan did not operate* Window is broken / non operational*	ď.				No / inadequate ventilation / heat*			
75 Bathtub  Appears serviceable  Damage / deterioration to tub*  Faucet appears serviceable  Hot & cold water reversed  Faucet / fixture: Leaks / corroded / damaged*  Drain appears serviceable  Slow draining at bathtub*  COMMENTS:					Not applicable to this bathroom			
Appears serviceable Damage / deterioration to shower walls* Grout / caulking needed at shower walls* Moisture damage to wall / floor ②③ Slow draining at shower*. Water valve(s) / shower head: Leaks / drips ② Hot & cold water reversed* ④ Enclosure appears serviceable Glass does not appear to be tempered* Broken glass / enclosure*. Caulking needed at doors / enclosure*					Not applicable to this bathroom			

0X2HFX1601

- KEY: 

  Recommend evaluation by a structural/geo-technical engineer
  - ② Recommend evaluation and repairs by a licensed contractor
  - 3 Refer to qualified termite report for further information
- This item is a safety hazard-correction is needed
- ⑤ Upgrades are recommended for safety enhancement
- \* This item warrants attention/repair or monitoring

- Electrical	Panal	ha de la company	mak	- Nva	here	ASA)
TO CONTINUE						
			11			
				·		· · · · · · · · · · · · · · · · · · ·
	24,		-			***************************************
		1			The state of the s	
						The second secon
				- Area		
			<del></del>			

KAPLAN 800-323-9235

copyright@

2000 LTA, REPRODUCTION OR UTILIZATION OF THIS REPORT WITHOUT WRITTEN AUTHORIZATION BY LTA, IS NOT PERMITTED

0X2HFX2601

